


## DIN 934 ZESKANTMOER



d	M2	M3	M4	M5	M6	M7	M8	M10	M12	M14	M16	M18	M20
p	0.4	0.5	0.7	0.8	1	1	1.25	1.5	1.75	2	2	2.5	2.5
m	1.6	2.4	3.2	4	5	5.5	6.5	8	10	11	13	15	16
s	4	5.5	7	8	10	11	13	17	19	22	24	27	30
e	4.38	6.08	7.74	8.87	11.05	12.12	14.38	18.90	21.1	24.49	26.75	30.14	33.53

d	M22	M24	M27	M30	M33	M36	M39	M42
p	2.5	3	3	3.5	3.5	4	4	4.5
m	18	19	22	24	26	29	31	34
s	32	36	41	46	50	55	60	65
e	35.72	39.98	45.63	51.28	55.8	61.31	66.96	72.61

—